

DAFTAR GAMBAR

| | |
|--|----|
| Gambar 2.1 Retak Kulit Buaya (<i>Alligator Cracking</i>) | 13 |
| Gambar 2.2 <i>Deduct Value</i> Retak Kulit Buaya (<i>Alligator Cracking</i>) | 14 |
| Gambar 2.3 Kegemukan (<i>Bleeding</i>) | 15 |
| Gambar 2.4 <i>Deduct Value</i> Kegemukan (<i>Bleeding</i>) | 16 |
| Gambar 2.5 Retak Kotak-kotak (<i>Block Cracking</i>) | 16 |
| Gambar 2.6 <i>Deduct Value</i> Retak Kotak-Kotak (<i>Block Cracking</i>) | 17 |
| Gambar 2.7 <i>Deduct Value</i> Retak <i>Bump and Sags</i> | 19 |
| Gambar 2.8 Keriting (<i>Corrugation</i>) | 19 |
| Gambar 2.9 <i>Deduct Value</i> Keriting (<i>Corrugation</i>) | 20 |
| Gambar 2.10 Amblas (<i>Depression</i>) | 21 |
| Gambar 2.11 <i>Deduct Value</i> Amblas (<i>Depression</i>) | 22 |
| Gambar 2.12 Retak Pinggir (<i>Edge Cracking</i>) | 22 |
| Gambar 2.13 <i>Deduct Value</i> Retak Pinggir (<i>Edge Cracking</i>) | 23 |
| Gambar 2.14 <i>Deduct Value</i> Retak Sambungan (<i>Joint Reflection Cracking</i>) | 24 |
| Gambar 2.15 <i>Deduct Value</i> Penurunan / Bahu (<i>Lane / Shoulder Drop Off</i>) | 25 |
| Gambar 2.16 <i>Deduct Value</i> (<i>Longitudinal and Transverse Cracking</i>) | 26 |
| Gambar 2.17 Tambalan (<i>Patching</i>) | 27 |
| Gambar 2.18 <i>Deduct Value</i> Tambalan (<i>Patching</i>) | 28 |
| Gambar 2.19 Pengausan (<i>Polished Agregat</i>) | 28 |

| | |
|--|----|
| Gambar 2.20 <i>Deduct Value</i> Pengausan (<i>Polished Agregat</i>) | 29 |
| Gambar 2.21 Lubang (<i>Potholes</i>) | 29 |
| Gambar 2.22 <i>Deduct Value</i> Lubang (<i>Potholes</i>) | 31 |
| Gambar 2.23 <i>Deduct Value</i> Perlintasan Rel Kereta (<i>Railroad Crossing</i>)..... | 32 |
| Gambar 2.24 Alur (<i>Rutting</i>) | 32 |
| Gambar 2.25 <i>Deduct Value</i> Alur (<i>Rutting</i>) | 33 |
| Gambar 2.26 Sungkur (<i>Shoving</i>)..... | 33 |
| Gambar 2.27 <i>Deduct Value</i> Sungkur (<i>Shoving</i>)..... | 34 |
| Gambar 2.28 <i>Deduct Value</i> Retak Bulan Sabit (<i>Slippage Cracking</i>) | 35 |
| Gambar 2.29 Mengembang (<i>Swell</i>)..... | 35 |
| Gambar 2.30 <i>Deduct Value</i> Mengembang (<i>Swell</i>)..... | 36 |
| Gambar 2.31 Pelepasan Butir (<i>Raveling and Weathering</i>)..... | 37 |
| Gambar 2.32 <i>Deduct Value</i> Pelepasan Butir (<i>Raveling and Weathering</i>)..... | 38 |
| Gambar 2.33 Koreksi Kurva untuk Jalan dengan Perkerasan Aspal | 40 |
| Gambar 2.34 Diagram Nilai PCI..... | 41 |
| Gambar 2.35 Pola Jaringan Drainase Siku..... | 48 |
| Gambar 2.36 Pola Jaringan Drainase Pararel..... | 49 |
| Gambar 2.37 Pola Jaringan Drainase <i>Grid Iron</i> | 49 |
| Gambar 2.38 Pola Jaringan Drainase Alamiah | 50 |
| Gambar 2.39 Pola Jaringan Drainase Radial..... | 50 |
| Gambar 2.40 Pola Jaringan Drainase Jaring-jaring..... | 50 |

| | |
|---|-----|
| Gambar 2.41 Metode Thiessen | 53 |
| Gambar 2.42 Metode Isohyet..... | 55 |
| Gambar 2.43 Saluran Bentuk Persegi | 75 |
| Gambar 2.44 Saluran Bentuk Trapesium | 76 |
| Gambar 2.45 Saluran Bentuk Segitiga | 78 |
| Gambar 3.1 Lokasi Penelitian | 83 |
| Gambar 3.2 <i>Flow Chart</i> Penelitian | 86 |
| Gambar 4.1 Luas Pengaruh Pos Curah Hujan..... | 89 |
| Gambar 4.2 Grafik Intensitas Hujan Rencana dalam 24 jam..... | 100 |
| Gambar 4.3 Trase Jalan, DTA dan Penggunaan Lahan | 101 |
| Gambar 4.4 Kondisi Drainase STA 2+400 – STA 2+500 | 104 |
| Gambar 4.5 Tampang Saluran Drainase STA 2+400 – STA 2+500..... | 105 |
| Gambar 4.6 Kondisi Drainase Setiap Segmen | 106 |
| Gambar 4.7 Kerusakan <i>Potholes</i> STA 3+900 – STA 4+000 | 107 |
| Gambar 4.8 <i>Deduct Value Potholes</i> | 108 |
| Gambar 4.9 <i>Deduct Value Aligator Cracking</i> | 109 |
| Gambar 4.10 <i>Deduct Value Lane/Sholuler Drop Off</i> | 110 |
| Gambar 4.11 <i>Corrected Deduct Value (CDV)</i> STA 3+900 – STA 4+000 | 112 |
| Gambar 4.12 <i>Rating</i> Setiap Segmen | 114 |
| Gambar 4.13 Persentase Kerusakan Nilai Kondisi Jalan | 116 |
| Gambar 4.14 Persentase Luasan Jenis Kerusakan Perkerasan Jalan..... | 117 |

| | |
|---|-----|
| Gambar 4.15 Grafik Uji Hipotesis | 121 |
| Gambar 4.16 Kondisi Drainase, Luas Kerusakan, dan Nilai PCI | 123 |